

Mackie Tech Support - MCU Pro MIDI Self-Test

Self-test mode will give a visual display that all buttons are sending and receiving the midi message generated by the unit.

1. Disconnect USB from the MCU Pro
2. Connect only one midi cable from the Main Out Port 2 back into Main in Port 2. (it's a loop back)



3. Hold the select buttons on channels' 1 & 2 during power on.



4. The unit will ask to select operating mode, push down on the V-Pot under "Mackie Control."



5. Once in Mackie control mode, you can press buttons and notice the corresponding LED illuminate. That means the unit is sending and receiving its own midi message. See example photos below:



Touching a fader illuminates the corresponding signal LED, showing the unit is sending/receiving its own "touch sensitivity" midi message:



Contact Us

If you are still having a setup issue, please contact us via email or phone so we can trouble shoot your setup.

Email: techmail@loudtechinc.com

Phone: 800-258-6883 Ext. 1632

We are open Monday – Friday, 8AM-4PM PST

